

# Kofax Communication Server

## TAXx Modules Overview

Version: 10.3.0

Date: 2019-12-13

The KOFAX logo is displayed in a bold, blue, sans-serif font. The letters are thick and closely spaced, with a clean, modern appearance.

© 2019 Kofax. All rights reserved.

Kofax is a trademark of Kofax, Inc., registered in the U.S. and/or other countries. All other trademarks are the property of their respective owners. No part of this publication may be reproduced, stored, or transmitted in any form without the prior written permission of Kofax.

# Table of Contents

<b>Chapter 1: TAxX Modules Overview.....</b>	<b>4</b>
<b>Chapter 2: Hardware Revisions of TAxX Modules.....</b>	<b>5</b>

## Chapter 1

# TAXX Modules Overview

TA00	Application Server Cabinet
TA01	Model 301 cabinet
TA04	Application Server Fan Module
TA05	Model 301 IDE adapter
TA06	Power Supply For AS1
TA08	Model 350 cabinet
TA10	TC Dual CPU Mainboard
TA11	TC Dual CPU Mainboard
TA12	TC Single CPU Mainboard
TA37	Single GSM Interface
TA40	Floppy Disk Drive
TA41	IDE Slim line CD-ROM Drive
TA42	IDE Slim line CD-ROM Writer
TA43	IDE Slim line DVD-R/RW Writer
TA44	IDE Slim line DVD-ROM Drive
TA45	IDE Hard Disk Drive
TA47	SCA/SCSI Hard Disk
TA48	SCA/SCSI Hard Disk
TA53	Dual Gigabit Ethernet Board
TA60	Application Server Backplane
TA63	Single Channel SCSI Controller
TA65	Zero Channel RAID Controller
TA90	System Attendant For AS1

## Chapter 2

# Hardware Revisions of TAxX Modules

TA04.00	10.Jun.02	First delivered version
TA05.00	25.Feb.04	First delivered version
TA06.00	12.Jun.02	Bicker EFRP-2303
.0A	24 Oct 2002	Modification because of mechanical problems
.10	26.Nov.02	Bicker EFRP-2303-603 (produced by Etasis)
.20	12.Jun.02	Etasis EFRP-2356
TA08.00	28.Jun.05	First delivered version
TA10.00	14.Aug.02	Tyan S2688UGN Thunder HESl-T / Rev. C
TA11.00	15 Mar 2003	Iwill DPX2-S320 / Rev. B
.0A	08.Apr.03	Iwill DPX2-S320 / Rev. C
.0B	31.Jul.03	Iwill DPX2-S320 / Rev. D
.0C	05.Nov.03	Iwill DPX2-S320 / Rev. E
TA12.00	15 Mar 2004	Iwill XP5T / Rev. 0.92
.0A	16 Mar 2004	Iwill XP5T / Rev. 1.00
.0B	24 Mar 2004	Iwill XP5T / Rev. 1.10
TA37.10	01.Apr.05	First delivered version
TA40.00	07 Oct 2002	TEAC FD-235HFE
TA41.00	05 Mar 2002	TEAC CD-244E
TA42.00	05 Mar 2002	Toshiba SD-R2102

.10	30 Jan 2003	TEAC CD-W224EA
TA43.00	04.Feb.03	Toshiba SD-R6012
.10	10.Nov.03	Toshiba SD-R6112
TA44.00	03 Oct 2003	TEAC DV-28E
TA45.00	17 Mar 2004	HITACHI HTS726060M9AT00 / FW: MH4OA68A
TA47.00	10.Jun.02	IBM IC35L073UCD210-0 / S5BA
.10	25.Jul.02	IBM IC35L073UCDY10-0 / S21E
.20	14 May 2003	Seagate ST373307LC / Rev. 004
TA48.00	14 May 2003	Seagate ST3146807LC / Rev. 004
TA53.00	14 May 2003	Intel PRO/1000 MT Dual Port Server Adapter
TA60.00	4 May 2002	Samples for Development
.1A	23.Jul.02	Modifications because of mechanical problems
.1B	02.Aug.02	Floppy disk connector type changed
.20	22.Aug.02	new PCB, mistakes in silkscreen corrected
.2A	17 Oct 2002	see .1C
.1C		SCL signal for TA90 from DrvSel0 rerouted to MotorOn0 (this prevents the FDD LED from flickering during TA90 accesses)
.2B	24.Apr.03	Problem that red LED may light although both fans are working properly solved.
TA63.00	11.Jul.03	Adaptec AHA-2940AU
TA65.00	24.Aug.02	Adaptec ASR-2000S / Rev. B
.10	02.Jun.03	Adaptec ASR-2010S / Rev. A